

## Humidity & Temperature Meter

Technical indicators	GM1360	GM1360A
Temperature range	-10~50°C	-30~80°C
Humidity range	5~98%RH	0~100%RH
Temperature measurement precision	±1°C or ±1.8°F	±1°C(±1.8°F), Typical temperature: ±3 (Max ±1°C)
Humidity measurement precision	±3%RH(25°C,20~80%RH); < ±5%RH(25°C,0~80%RH, 80~100%RH)	±3%RH(25°C,20~80%RH); < ±5%RH(25°C,0~80%RH, 80~100%RH)
Temperature resolution	0.1°C/0.1°F	0.1°C/0.1°F
Humidity resolution	0.1%RH	0.1%RH
Sampling frequency	2.5 times/SEC	1 times/SEC
Operating environment	0 ~50°C (32 ~122°F) ≤80%RH No condensation	0 ~50°C (32 ~122°F) ≤80%RH No condensation
Storage environment	-10~60°C (14 ~140°F) 0%RH~90%RH	-30~80°C (-22 ~104°F) 0%RH~90%RH
<b>Peculiarity</b>		
Large screen display	√	√
Temperature & humidity measurement	√	√
Dew point temperature measurement	×	√
Max/min temperature & humidity values	√	√
°C/°F Selection	√	√
Keeping data	√	√
USB interface Settings & data download	×	√
Temperature & humidity recorder	×	√
Low electric lift	√	√
Automatic/manual to turn it off	√	√
<b>Conventional</b>		
Power supply	9V batteries	
Product size	207*70*30mm	
Product weight	199.7g (+batteries)	
Standard Quantity Per Carton	20PCS	
Standard Carton Size	67.5*45.8*30.2cm	
Standard Carton Gross Weight	16.9kg	17.6kg



GM1360



GM1360A